

FIG.2









FIG.3












*FIG.* 7







FIG.9



Recording command received 1001

Adjustment executed in the adjustment—only area in the vicinity of the recording instruction area indicated by the recording command

Recording command executed 1003











FIG. 12
































FIG. 24

